

# GCL serves as cap in Brownfield remediation site

This New Jersey Brownfield was formerly the site of a chemical recycling facility.



### PROJECT DETAILS

New Jersey Brownfield Remediation

### LOCATION

Patterson, New Jersey

### PRODUCTS USED

BENTOMAT® SDN

This New Jersey brownfield was formerly the site of a chemical recycling facility.

#### CHALLENGE:

The soil at the site was heavily contaminated, and off-site removal would have been extremely costly. High winds and very cold weather also posed a problem.

#### SOLUTION:

The site was surrounded with a soil-bentonite slurry wall and topped with a six-acre geosynthetic cap. The geosynthetics were terminated at a corrugated sheet pile wall. Cast-in-place concrete with an embedded polyethylene strip was added to which the LLDPE geomembrane was welded. The BENTOMAT SDN liner held up well in the high winds.

#### RESULT:

The contaminated soil was successfully contained, preventing it from spreading to surrounding areas. Everything was completed on time and within budget.

North America: 847.851.1800 | 800.527.9948 | [www.cetco.com](http://www.cetco.com)

UPDATED: SEPTEMBER 2017

© 2017 Minerals Technologies Inc. IMPORTANT: The information contained herein supersedes all previous printed versions, and is believed to be accurate and reliable. For the most up-to-date information, please visit [www.cetco.com](http://www.cetco.com). CETCO accepts no responsibility for the results obtained through application of this product. CETCO reserves the right to update information without notice.

